

Daniel E. Drake
Interim Chief Operations
Officer



Dr. R. Stephen Green
Superintendent

Operations Division – Sam Moss Service Center

1780 Montreal Road
Tucker, Georgia 30084-6705
(678) 676-1320

Re: New Play Structure at Henderson Mill Elementary School

Dear Parents,

The DeKalb County School District would like to apprise you of the situation regarding the play structure at your child's school. Installation of the new playground equipment and rubber play surface is complete. However, there is a low hanging AT&T cable in the vicinity of the new play structure. In an abundance of caution, the Operations Division will not allow the use of the new play structure until this cable is raised to an appropriate height. The DCSD Maintenance Department is currently scheduling this work with the appropriate vendor. Once the cable has been raised, the Operations Division will notify the Principal that the play structure may be used. The Operations Division apologizes for any inconvenience this delay may cause.

Respectfully,

Richard H. Boyd
Director, Design and Construction
DeKalb County School District

cc: Daniel E. Drake
Trenton Arnold
Principal Moore
Lemuel Hawkins